

LEE'S AUTOMOTIVE REPAIR

BAR #: ARD250924

CAL 922673697

11273 WHITE ROCK RD

RANCHO CORDOVA, CA 95742

Phone: 916-852-6414 FAX: 916-852-6431

Invoice No.

72017

Page 1

Order Date 06/27/17 02:59 pm

Paid: 12/30/99 12:00 am

Ref: FIN CALLED

ASK ABOUT OUR TIRE SPECIALS !!!!!**DOJ/BFS**

11181 SUN CENTER DR.

RANCHO CORDOVA CA 95670

HOWARD [REDACTED]

OFFICE: 916-210-5421

02 CHEV. (ATC) P-30 WHITE

Mileage in:11622 out:

Lic: [REDACTED] CA V8Cyl 5.7 Eng

Vin: [REDACTED]

Eq:

Fleet # 90012922

Job01 RADIATOR INSPECTION**Labor: 1.00 hrs @ \$108.00/hr= N/C**

RADIATOR HOSE ON THE INTAKE SIDE POPPED OFF WHILE DRIVING. CLAMP ON HOSE WAS LOOSE AND DOES NOT LOOK LIKE IT IS THE CORRECT ON FOR THE HOSE. CUSTOMER REATTACHED HOSE BEST THEY COULD AND TOPPED OFF COOLING SYSTEM WITH A DIFFERENT KIND OF FLUID. CHECK HOSE FOR CRACKS AND REPLACE CLAMP.

NOTES FOR TECH: CUSTOMER WOULD LIKE THE RADIATOR FLUID CLEANED UP AS IT MADE A MESS WHEN THE HOSE CAME OFF.

Tech Notes For Customer: Replaced spring clamp with band clamp. Tested for leaks no leaks at this time. cleaned engine bay for coolant mess.

Status: Completed Tech: IH

Job02 COOLING SYSTEM FLUSH**Labor: 1.25 hrs @ \$108.00/hr= N/C**

GLOBAL

COOLANT-N (List 23.95)

3.0 @

20.37 =\$

N/C

DRAIN & FLUSH COOLING SYSTEM WITH NEW FLUID. TEST FOR LEAKS AND OPERATION.

Tech Notes For Customer: Flushed cooling system used new coolant. Tested for leaks no leaks at this time.

Status: Completed Tech: IH

Job03 HYDRAULIC LIFT SYSTEM**Labor: 1.00 hrs @ \$108.00/hr= N/C**

HYDRAULIC LIFT SYSTEM INSTALLED BY US. THE SYSTEM IS GIVING OUT AN ERROR MESSAGE WHEN THE AUTO LEVEL IS ENGAGED. CUSTOMER IS MANUALLY PUTTING THE LEGS DOWN TO THE BLOCKS AND THEN HITTING THE AUTO LEVEL BUTTON. IS THERE ANOTHER PROCEDURE NEEDED TO FOLLOW? CHECK AND ADVISE.

----->----->----->---Continued on the next page--->----->----->

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

9/6/17

LEE'S AUTOMOTIVE REPAIR

BAR #: ARD250924

CAL 922673697

11273 WHITE ROCK RD

RANCHO CORDOVA, CA 95742

Phone: 916-852-6414 FAX: 916-852-6431

Invoice No.

72017

Page 2

Order Date 06/27/17 02:59 pm

Paid: 12/30/99 12:00 am

Ref: FIN CALLED

ASK ABOUT OUR TIRE SPECIALS !!!!!**Job03 HYDRAULIC LIFT SYSTEM**

Tech Notes For Customer: Performed zero point calibration per service Manuel and now there is no more error codes and auto level works properly at this time.

Status: Completed Tech: BWF

Job04 MANUAL LEG INSPECTION

Labor: 1.00 hrs @ \$108.00/hr= N/C

LEVER & ROD ASSEMBLY USED TO PUT THE LEGS DOWN GETS STUCK AFTER SETTING. THE BOLT HOLES THAT THE ROD SLIDES THROUGH APPEAR TO HAVE MISSHAPEN FOR AN "O" TO AN OBLONG SHAPE THAT ALLOWS THE ROD TO SIT IN A SORT OF DITCH. POSSIBLE THIS WAS CAUSED BY OVERLOADING THE LEGS AND IS THE RESULT OF THE LEVER GETTING STUCK IN THIS "DITCH." CHECK AND ADVISE SYSTEM IS SUITED AND APPROPRIATE FOR DOJ USE.

Status: Completed Tech: BWF

Job05 DRIVER MIRROR INSPECTION

Labor: 1.00 hrs @ \$108.00/hr= N/C

DRIVER MIRROR WAS REINSTALLED WITH A NEW GROMMET & BOLT. WHILE DRIVING, THE MIRROR WILL FLEX AND DOESN'T HOLD STEADY DUE TO WIND. SEE IF WE CAN MAKE A STURDIER BASE TO HOLD THE MIRROR IN PLACE WHILE LEAVING THE ADJUSTABILITY AVAILABLE.

Tech Notes For Customer: Snugged bolts on mount a little more. (Still adjustable) test drove up to 70 mph. Mirror stays in place.

Status: Completed Tech: BWF

Job06 TIRE INSPECTION

Labor: 0.10 hrs @ \$108.00/hr= N/C

TIRES MAY BE TOO THIN FOR THE VEHICLE. CHECK AND ADVISE.

Tech Notes For Customer: Checked vin plate says tire size is 8r 19.5. Tire are 8r 19.5. Tires are manufactor recommended.

Status: Completed Tech: BWF

Job07 RADIO INSPECTION

Labor: 1.00 hrs @ \$108.00/hr= N/C

----->----->----->---Continued on the next page--->----->----->----->

Page 3

BAR #: ARD250924

72017

Order Date 06/27/17 02:59 pm

CAL 922673697

Paid: 12/30/99 12:00 am

11273 WHITE ROCK RD

Ref: FIN CALLED

RANCHO CORDOVA, CA 95742

Phone: 916-852-6414 FAX: 916-852-6431

ASK ABOUT OUR TIRE SPECIALS !!!!!

Job07 RADIO INSPECTION

RADIO DOES NOT WORK. IT SEEMS TO TURN ON BUT DOES NOT FUNCTION. CHECK AND ADVISE.

Tech Notes For Customer: Radio was hooked up to aux remote power. So radio would only work when aux power switch was in. Hooked remote wire up to ign power supply fuse block under dash and now radio comes on when ign is turned on. Advise customer the radio does not come on when aux power is on or if ign is not on

Status: Completed Tech: BWF

Job08 MANUAL LIFT REPAIR

Labor: 3.00 hrs @ \$108.00/hr= N/C

BOLT

PIN-S

2.0 @

29.52 = \$

N/C

INSTALL BIGGER ROD ASSEMBLY AND DRILL OUT HOLES TO MATCH. WELD CHAINS TO THE ROD ASSEMBLY.

Tech Notes For Customer: After relocating leveling module and installing bigger pins auto level works as its supposed to at this time.

The system will not level if vehicle if front to back is not relatively level. Will level if side to side is somewhat not level. Really need to read the Manual and understand the leveling system is for a fifth wheel or motor home and those are generally start on somewhat level ground.

Status: Completed Tech: BWF

Job09 WASH VEHICLE

Labor: 1.00 hrs @ \$108.00/hr= N/C

WASH VEHICLE FOR CUSTOMER PICKUP.

Status: Completed Tech: ML

Recommendations: USE 916-207-3435 HOWARD

Tire Pressure: LF[] RF[] LR [] RR []

I acknowledge notice &
oral approval of an
increase in the
original estimated price

----->----->----->-----Continued on the next page----->----->----->----->

LEE'S AUTOMOTIVE REPAIR

BAR #: ARD250924

CAL 922673697

11273 WHITE ROCK RD

RANCHO CORDOVA, CA 95742

Phone: 916-852-6414 FAX: 916-852-6431

Invoice No.

72017

Page 4

Order Date 06/27/17 02:59 pm

Paid: 12/30/99 12:00 am

Ref: FIN CALLED

ASK ABOUT OUR TIRE SPECIALS !!!!!**SIGNATURE**

Warranty on parts and labor is 1 year or 12000 mileage whichever comes first unless otherwise specified on repair order detail. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Exclusions are general wear items (i.e.: fluids and filters, brake pads and rotors), and trim pieces. Customer supplied parts do not receive any warranty, nor do used parts other than a possible warranty on the part (not labor) directly from the vendor.

Payments to LEE'S AUTOMOTIVE REPAIR**Cost Summary**

Status: Paid Work Order

Payments:

1 09/06/17 0.00 Other

Labor	0.00
Parts	0.00
Subtotal	0.00
Total	\$0.00
Payments	0.00
Bal Due	0.00

Thank you for choosing LEE'S AUTOMOTIVE REPAIR